Multifamily Rental Housing Field Inspections

Data: March 2024

Bridget Lawlor, GIS Manager



Statistics

- Within the City limits of Sandy Springs:
 - There are currently 98 apartment complexes with 2 more currently in development
 - There are approximately 1,300 structures
 - There are over 25,000 rental units
 - Represents an estimated 50,000 to 75,000 residents
 - 70% of apartments are 20 years old or older
 - 47% do not have an automatic sprinkler system
 - 25% are partially sprinklered
 - 28% are fully sprinklered






What's The Purpose Of An MRH Ordinance?

- The purpose of the MRH Ordinance:
 - <u>To ensure</u> structural strength, means of egress facilities, stability, sanitation, adequate light and ventilation, energy conservation, and safety to life and property from fire, explosion, and other hazards
 - To provide a reasonable level of safety to firefighters and emergency responders during emergency operations





From this ...


InspectText	Group
All exterior entry doors are operational and properly aligned and installed in the door frame (Provide "failed" location(s) if	
applicable).	Doors / Windows
All <u>exterior entry doors have privacy locks</u> and are in good working order (<u>Note</u> : No double-keyed locks are allowed).	Doors / Windows
All exterior entry doors providing access to egress corridors, breezeways, or stairs are self-closing and fully latch.	Doors / Windows
All <u>interior doors are operational</u> and properly aligned and installed in the door frame (Provide "failed" location(s) if applicable).	Doors / Windows
Bathroom doors have privacy locks and are in good working order (Note: No double-keyed locks are allowed).	Doors / Windows
All bedrooms have windows that are operable.	Doors / Windows
All windows shall be in good condition with no cracks, broken seals, or holes.	Doors / Windows
Exterior <u>balconies, decks, and/or porches are structurally sound</u> and maintained in good condition (i.e., properly secured no evidence of wood rotting, etc.).	, Balcony / Deck / Porch
All <u>guardrails,</u> located on exterior balconies, decks, and/or porches <u>are a minimum height of 36</u> " and are maintained in <u>good condition</u> (i.e., properly secured, no evidence of rust, wood rotting, etc.).	Balcony / Deck / Porch
No open-flame cooking devices (i.e., grills, turkey fryers, etc.) are located on the balcony. Exception: Grills are only allowed on balconies that are sprinklered and are made of non-combustible materials on all surfaces (unless not allowed	
by property management).	Balcony / Deck / Porch
All <u>stairs and landings are structurally sound</u> and maintained in good condition.	Structural
All <u>stairs and landings have a continuous and graspable handrail</u> that is properly secured to the wall and/or structure. <u>Note</u> : Handrail only required on 4 or more risers.	Structural
Interior floors and ceilings are level and in good condition (check to make sure there are no sags, humps, or cracks).	Structural
Interior walls are plumb and are in good condition (check to make sure there are no cracks in the finishes).	Structural
There is <u>no evidence of insects and/or rodents</u> observed. (Note: extermination is required prior to re-leasing a vacant unit)	Environmental
There is <u>no presence of mold or mildew</u> inside the unit.	Environmental
There is <u>no evidence of water staining</u> on the unit's ceilings, walls, and/or floors.	Environmental
Smoke detector located in all sleeping rooms.	Life Safety
Smoke detector located <u>on the ceiling or wall outside of each separate sleeping area in the immediate vicinity of</u> bedrooms.	Life Safety
Smoke detectors are less than 10 years old (Enter the expiration date in the required action).	Life Safety
All existing smoke detectors are operational (press the test button).	Life Safety
All existing smoke detectors are interconnected so that the activation of one alarm will activate all alarms.	
Note 1: Smoke detectors are required to be interconnected once they expire and are replaced.	Life Safety
Carbon monoxide detector installed (only required for fuel gas appliances such as stove, furnace, water heater, fireplace etc.)	, Life Safety
•	Life Safety



To This ...








Live Inspection Results

Esri, TomTom, Garmin, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS,



North Druid

Powered by Esri

ARIUM MORGAN FALLS - 8060, 8085, AND 8090 ADAIR LN


Inspection Details

CBI Unit Inspections

Failed

Passed

Pending 24,132




Conclusion

Inspectors record unit details in the field.

Pictures are stored with the unit.

Community Development sees the inspection results real-time.

Easy to communicate data with stakeholders.



Thank you